


Vinyl Application instructions

Surface


The surface should be cleaned prior to application of vinyls, often used degreasants are white spirit, or a metholated spirit.

Temperature Requirements


Air and application surface temperatures are to be above 40 degrees F.




Use masking tape to position lettering



Remove one side of masking tape




Fold back carrying paper
(With lettering attached)
Cut off and discard backing paper



Carefully rub down lettering to
surface with squeegee




Remove remaining masking tape



Fold back carrying paper
(With lettering attached)
Cut off and discard remaining backing paper



Carefully rub down lettering to
surface with squeegee



Carefully pull back the carry paper
on itself to reveal your vinyl